Basic Detail Report



Silo 4: Oxford Road, New Hartford, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 4: Metal, 18' x 15.5', built c. 1940, not currently in use. Half of the silo has been taken down. Image of a large wooded barn with a tractor trailer parked along it. Behind the tractor cab there is a silo with no top. There are three paths plowed in the snow in front of the barn. Between the two paths on the right there is a large evergreen tree.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)