



9265.9 cm, 180PPI)

## Silo 5 & 6: Sessions Road, New Hartford, NY

**Date**

2013-14

**Medium**

Digital image Jpeg

**Description**

Silo 5: Concrete Stave, 50' x 14", built in 1920, not currently in use. Silo 6: Concrete Stave, 60' x 15', built c. 1980, not currently in use. Image of two silos at the corner of a white barn with an arched roof. There are shrubs growing at the base of the silo. The one in the back is shorter than the other.

**Dimensions**

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 ×