

# Basic Detail Report

---



## **Silos 14-17: Mallory Road, New Hartford, NY**

### **Date**

2013-14

### **Medium**

Digital image Jpeg

### **Description**

This farm is one of last 2 operating dairy farms in New Hartford, 60 cows. Silo 14: Concrete Stave, 60' x 24', built c. 1969, currently in use. Silo 15: Concrete Stave, 50' x 16', built c. 1972, currently in use. Silo 16: Concrete Stave, 50' x 16', currently in use. Silo 16 was originally a Harvestore, then it started to leak and rust, so they took it down and put concrete on its base (cheaper than removing the base) Silo 17: Concrete Stave, 50' x 16', currently in use. Image of a barn with three silos to the right of it and one to the left of it. The image also looks out over the snow covered corn fields. They are all made of cement blocks and have white domed roofs. The barn also has a red, white, and blue barn quilt tile on the side of it. There are foot prints in the snow leading to where the photo is taken from.

### **Dimensions**

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)