Basic Detail Report



Silos 14-17: Mallory Road, New Hartford, NY

Date

2013-14

Medium

Digital image Jpeg

Description

This farm is one of last 2 operating dairy farms in New

Hartford, 60 cows. Silo 14: Concrete Stave, 60' \times 24', built c. 1969, currently in use. Silo 15: Concrete Stave, 50' \times 16', built c. 1972, currently in use. Silo 16: Concrete Stave, 50' \times 16', currently in use. Silo 16 was originally a Harvestore, then it started to leak and rust, so they took it down and put concrete on its base (cheaper than removing the base) Silo 17: Concrete Stave, 50' \times 16', currently in use. Image looking up at three silos each with a dome roof..

Dimensions

Digital Resolution: 2736×3648 in., 180PPI (6949.5×9265.9 cm, 180PPI)