# **Basic Detail Report**



# Silos 14-17: Mallory Road, New Hartford, NY

#### **Date**

2013-14

## Medium

Digital image Jpeg

## Description

This farm is one of last 2 operating dairy farms in New Hartford, 60 cows. Silo 14: Concrete Stave, 60' x 24', built c. 1969, currently in use. Silo 15: Concrete Stave, 50' x 16', built c. 1972, currently in use. Silo 16: Concrete Stave, 50' x 16', currently in use. Silo 16 was originally a Harvestore, then it started to leak and rust, so they took it down and put concrete on its base (cheaper than removing the base) Silo 17: Concrete Stave, 50' x 16', currently in use. Image of three silos next to each other

along the side of a barn. There is a door in between the first two, and a hay escalator between the second two. There is another piece of farm equipment parked in front of the middle silo.

#### **Dimensions**

Digital Resolution:  $2736 \times 3648$  in., 180PPI ( $6949.5 \times 9265.9$  cm, 180PPI)