Basic Detail Report



9265.9 cm, 180PPI)

Silo 22: Roberts Road, New Hartford, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 22: Monolithic Concrete, $40' \times 16'$, not currently in use. Image of a silo between two barns. They are both sided with metal. There is no domed top on the silo and the roves are covered in snow. The barn closer to the the to camera looks to be equiptment storage with two open doors. The other barn's from sliding door is partially open. There are mounds of evergreen bows around the yard covered in snow.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times