

Basic Detail Report



Silo 23: Grange Hill Road, New Hartford, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 23: Concrete Stave, 40' x 16', c. 1900's, not currently in use. Image looking up a silo shoot that is partially covered.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)