

# Basic Detail Report

---



## Silos 32-34: Roberts Road, Paris, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 32: Concrete Stave, c. 1979, currently in use. Silo 33: Concrete Stave, c. 1950, not currently in use. Silo 34: Monolithic Concrete, c. 1990, currently in use. Image of a large white barn with three silos to the left of it. The front silo is much taller than the other two. The silo in the middle is shorter than the other two. There is a tractor and another piece of equipment parked at the base of the silos. There is the corner of another barn in the left corner of the photo and a truck parked in front of the white barn. There is snow on the ground with tire tracks

through it.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)