Basic Detail Report



Silos 35 & 36: Campbell Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 35: Concrete Stave, 40' x 16', c. 1950, not currently in use. Silo 36: Monolithic Concrete, 40' x 20', c. 1940, not currently in use. Image of two silos along two different barns. The silo to the left is much smaller. There is a thrid barn along the left side of the photo. There are tractors and trucks parked in the snowy yard.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times

9265.9 cm, 180PPI)