Basic Detail Report



Silos 41 & 42: Bray Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 41: Concrete Stave, 40' \times 16', not currently in use. Silo 42: Concrete Stave, 40' \times 16', not currently in use. Image of two silos along the front of a barn. There is a small addition off the barn to the left of the silos. The ground is covered in snow that is plowed out from in front of the barn and silos. There are two trucks parked in front of the barn.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)