

Basic Detail Report



Silos 50 & 51: Sulphur Springs Road, Paris NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 50: Concrete Stave, 45' x 18', not currently in use.

Silo 51: Concrete Stave, 45' x 18', not currently in use.

Image of two silos standing next to a barn that is starting to fall down. There are other smaller buildings around the large barn and silos. The photo is taken from a plowed road, there is a guard rail at the bottom of the photo. The ground is covered in snow.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)