



9265.9 cm, 180PPI)

Silos 92-94: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 92: Concrete Stave, 40' x 18', c. 1980, currently in use. Silo 93: Concrete Stave, 60' x 18', c. 1970, currently in use. Silo 94: Metal, 35' x 15.5', c. 1950, currently in use. Image of three silos along the side of a long barn. The middle silo is much taller than the other two, but they are all made of cement. The portion of the barn to the left is red metal-sided, and to the right has no siding. There are farm utensils scattered around the snowy barn yard.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 ×