## **Basic Detail Report**



# Silos 100 & 101: Route 8, Brookfield, NY

#### **Date**

2013-14

#### Medium

Digital image Jpeg

### Description

Silo 100: Concrete Stave, 80' x 20', c. 1978, currently in use. Silo 101: Concrete Stave, 70' x 20', c. 1950, currently in use. Image of a short long barn with a tall silo at the end. It has a cage ladder on the side of it. The barn has a few panels of siding missing and there is a tractor and manure spreader parked along side the barn. There are tractor tire tracks all around the barn in the snow.

### **Dimensions**

Digital Resolution: 2736  $\times$  3648 in., 180PPI (6949.5  $\times$  9265.9 cm, 180PPI)