

Basic Detail Report



Silos 102 & 103: County Highway 18A, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 102: Wooden Stave, not currently in use. Silo 103: Wooden, not currently in use. Image of a large barn with a domed roof. The back half of the barn is red. There is a non-functional silo to the right of the barn and a useable one on the left. The yard around the barn is covered in snow and the land closer to the camera is grown up with shrubs and small trees.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)