

# Basic Detail Report

---



## Silos 106 & 107: Route 8, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 106: Metal, 30' x 14' c. 1930, not currently in use. Silo 107: Concrete Stave, 40' x 16', c. 1970, not currently in use. Image looking down the side of a road to a barn with

two silos. The road is labeled at 8 north and the barn sits right along the road. There is a silo at each side end of the barn.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)