

Basic Detail Report



Silos 32-34: Roberts Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 32: Concrete Stave, c. 1979, currently in use. Silo 33: Concrete Stave, c. 1950, not currently in use. Silo 34: Monolithic Concrete, c. 1990, currently in use. Image of a

green tractor and green manure spreader parked at the base of a silo. There is a white barn behind them, with metal siding and roofing.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)