

Basic Detail Report



Silos 35 & 36: Campbell Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 35: Concrete Stave, 40' x 16', c. 1950, not currently in use. Silo 36: Monolithic Concrete, 40' x 20', c. 1940, not currently in use. Image of a silo in front of a large red barn that's paint is wearing off. There is a sod ramp leading to the front double doors. Parked in front of the silo there is a cage tank, a wagon, a boat, and a van.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)