Basic Detail Report



Silos 44-47: Sulphur Springs Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 44: Sealstor, 25' x 18', c. 1980, not currently in use.

Silo 45: Concrete Stave, $50' \times 18'$, c. 2000, not currently in use. Silo 46: Monolithic Concrete, $50' \times 18'$, c. 1980, not currently in use. Silo 47: Concrete Stave, $30' \times 16'$, c. 1960, not currently in use. Image of four silos, two the same height, and two shorter ones. The silo to the left is blue and wide while the one to the right is cement like the two taller ones. They sit in front of a large blue metal sided barn. In front of them there is a truck camper that has a for sale sign in its back window.

Dimensions

Digital Resolution: 2736×3648 in., 180PPI (6949.5×9265.9 cm, 180PPI)