

Basic Detail Report



9265.9 cm, 180PPI)

Silo 66: Canning Factory Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 66: Concrete Stave, 60' x 18', not currently in use. Fire in 1992 burned the barn down and damaged the silo chute. Image of a topless cement silo along side of a barn with metal siding and roofing. There is a larger L-shaped barn with a green metal rood around the smaller one. There are two grain bins on either side of the smaller barn. There is a horse trailer and other equiptment parked around the barns.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 ×