

# Basic Detail Report

---



## Silo 66: Canning Factory Road, Paris, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 66: Concrete Stave, 60' x 18', not currently in use. Fire in 1992 burned the barn down and damaged the silo chute. Image of a grain bin in front of a tan and green

metal sided barn. There are tires, barrels, and other items scattered around the grain bin. There is another building made of cement to the left of the grain bin.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)