Basic Detail Report



Silo 67: Summit Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 67: Concrete Stave, 40' x 16', c. 1950, not currently in use. Image of a silo standing by itself next to the ruin of a barn. It has a large whole at the top of the cement just under the domed roof. The crop shoot along the side of the silo is also falling apart at the bottom. There is part of the stone foundation of the barn still stands. The gorund and ruins are covered in snow.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)