# **Basic Detail Report**



## Silo 67: Summit Road, Paris, NY

#### **Date**

2013-14

#### Medium

Digital image Jpeg

### Description

Silo 67: Concrete Stave,  $40' \times 16'$ , c. 1950, not currently in use. Image of a silo standing by itself next to the ruin of a barn. It has a large whole at the top of the cement just

under the domed roof. The crop shoot along the side of the silo is also falling apart at the bottom. There is part of the stone foundation of the barn still stands. The gorund and ruins are covered in snow.

### **Dimensions**

Digital Resolution:  $2736 \times 3648$  in., 180PPI ( $6949.5 \times 9265.9$  cm, 180PPI)