

Basic Detail Report



Silos 69-71: Marshall Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 69: Concrete Stave, 70' x 20', c 1970, not currently in use. Silo 70: Concrete Stave, 60' x 18', c 1970, not currently in use. Silo 71: Concrete Stave, 70' x 20', c

1970, not currently in use. Image looking at the bottom of two cement silos and the red metal sided barn beyond them. The barns foundation is made of cement blocks and has glass block windows in it. There is snow piled in front of the barn and some around the bottom of the silos.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)