

Basic Detail Report



Silos 69-71: Marshall Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 69: Concrete Stave, 70' x 20', c 1970, not currently in use. Silo 70: Concrete Stave, 60' x 18', c 1970, not currently in use. Silo 71: Concrete Stave, 70' x 20', c

1970, not currently in use. Image of a cement block walled barn. There is a fan built into the top of the wall. There is snow and wood scraps on the ground around the barn.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)