

Basic Detail Report



9265.9 cm, 180PPI)

Silos 69-71: Marshall Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 69: Concrete Stave, 70' x 20', c 1970, not currently in use. Silo 70: Concrete Stave, 60' x 18', c 1970, not currently in use. Silo 71: Concrete Stave, 70' x 20', c 1970, not currently in use. Image of two silos along a cement walled barn. The silo on the left is taller and wider than the other. The barn next to it has some red metal siding on it as well. There is a second red metal sided barn in front of the silos.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 ×