

Basic Detail Report



Silos 69-71: Marshall Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 69: Concrete Stave, 70' x 20', c 1970, not currently in use. Silo 70: Concrete Stave, 60' x 18', c 1970, not currently in use. Silo 71: Concrete Stave, 70' x 20', c 1970, not currently in use. Image of two cement silos on either side of an entrance to a barn that is shaped like an L. There is another barn straight across from the silos. Both barns are red metal sided. There is a light layer of snow on the ground with many tire tracks through it, exposing dirt driveway.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)