# **Basic Detail Report**



# Silos 69-71: Marshall Road, Paris, NY

### **Date**

2013-14

#### Medium

Digital image Jpeg

## Description

Silo 69: Concrete Stave, 70' x 20', c 1970, not currently in use. Silo 70: Concrete Stave, 60' x 18', c 1970, not currently in use. Silo 71: Concrete Stave, 70' x 20', c 1970, not currently in use. Image looking up a cement silo that has red metal sided barn on either side of it.

### **Dimensions**

Digital Resolution: 2736  $\times$  3648 in., 180PPI (6949.5  $\times$  9265.9 cm, 180PPI)