

# Basic Detail Report

---



## Silos 72-74: Marshall Road, Paris, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 72: Concrete Stave, 32' x 20', currently in use. Silo 73: Concrete Stave, 40' x 20', currently in use. Silo 74: Concrete Stave, 40' x 18', currently in use. Image looking

at some sort of grain moving equipment that is set next to the base of a silo with wooden beams supporting it. Used for storage (soybeans, shell corn) not for silage.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)