Basic Detail Report



Silos 72-74: Marshall Road, Paris, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 72: Concrete Stave, 32' x 20', currently in use. Silo 73: Concrete Stave, 40' x 20', currently in use. Silo 74: Concrete Stave, 40' x 18', currently in use. Image looking

up at two cement silos with white domed rooves. There is snow falling onto the camera. Used for storage (soybeans, shell corn) not for silage.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)