

Basic Detail Report



Silo 75: NY Route 8, Bridgewater, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 75: Concrete Stave, 45' x 16' not currently in use.
Image looking across a road to an abandoned silo
surrounded by small trees and shrubs. To the left of it

there is a fence and a building tucked behind leafless trees. There is snow on the ground but not on the road.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)