Basic Detail Report



Silos 92-94: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 92: Concrete Stave, $40' \times 18'$, c. 1980, currently in use. Silo 93: Concrete Stave, $60' \times 18'$, c. 1970, currently in use. Silo 94: Metal, $35' \times 15.5'$, c. 1950, currently in use. Image of two silos at the side of a red, metal-sided barn. The silo on the left is much shorter than the other and there is some sort of farm utensil on the ground in front of them, covered in snow.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)