

# Basic Detail Report

---



## Silos 92-94: Route 8, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 92: Concrete Stave, 40' x 18', c. 1980, currently in use. Silo 93: Concrete Stave, 60' x 18', c. 1970, currently in use. Silo 94: Metal, 35' x 15.5', c. 1950, currently in

use. Image of the bottom of a cement silo along a barn with no siding. There is snow on the ground and the rungs of the silo. Beyond the barn, there is a tan house on the far side of a snow-covered field.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)