Basic Detail Report



Silos 95-98: County Highway 18, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 95: Concrete Stave, c. 1970, not currently in use. Silo 96: Clay Tile, c. 1920, not currently in use. Silo 97: Concrete Stave, c. 1960, not currently in use. Silo 98: Concrete Stave, c. 1970, not currently in use. Image of three silos in front of a barn. The two silos to the left share a roof. The one furthest to the left is made of orange cement blocks while the other two are made of regular cement. The silo to the right is taller than the other two. A girl stands in front of the tallest silo and a tractor parked

in front of the silo on the left.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)