Basic Detail Report



Silo 99: Lovers Lane, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 99: Concrete Stave, 60' x 20', not currently in use. Image of a cement silo in front of a barn. The base is surrounded by farm clutter, weeds, and snow. There is a grain bin to the left of the silo and a red hay wagon in front of it.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)