

Basic Detail Report



Silos 100 & 101: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 100: Concrete Stave, 80' x 20', c. 1978, currently in use. Silo 101: Concrete Stave, 70' x 20', c. 1950, currently in use. Image of a large pile of silage under a silage shoot inside of a barn.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)