

Basic Detail Report



Silo 105: Miner Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 105: Concrete Stave, 50' x 20', c. 1977, not currently in use. Image of a tattered barn with a larger barn and silo behind it. The larger barn has a plain steel roof while the tattered barn's roof is green. There is a house partially in frame to the left of the barns. There is a large portion of lawn that is covered in reed grass between the buildings and camera.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)