Basic Detail Report



Silos 106 & 107: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 106: Metal, 30' \times 14' c. 1930, not currently in use. Silo 107: Concrete Stave, 40' \times 16', c. 1970, not currently in use. Image of a barn that sits along side of a road. There

is one silo on each side of the barn. The addition off the barn closets to the camera is starting to cave in. The weeds and shurbs are grown up all around the barn. There is snow covering the landscape and the rooves of the barn and silos.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)