

Basic Detail Report



Silos 106 & 107: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 106: Metal, 30' x 14' c. 1930, not currently in use. Silo 107: Concrete Stave, 40' x 16', c. 1970, not currently in use. Close up image of the top of a silo and peak of the

barn it is next to. There is a small window at the top of the barn roof and a chimney above that. There is snow on the silo and barn rooves.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)