Basic Detail Report



Silo 108: County Highway 18, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 108: Wooden Attached, 16' x 16', not currently in use.

Image of red wood barn siding that is starting to fall apart. The barns surroundings are covered in snow.

Dimensions

Digital Resolution: 2736×3648 in., 180PPI (6949.5×9265.9 cm, 180PPI)