
Basic Detail Report



Silos 130-132: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 130: Harvestore, 40' x 18, c. 1982, not currently in use. Silo 131: Clay Tile, 30' x 16', not currently in use. Silo 132: Concrete Stave, 60' x 20', c 1950, not currently in use. Image of a barn and two silos with a large white house behind it. The clay tile silo to the lelft is half the height and falling down. It has no roof. There is snow on the ground with tractor tire tracks through it.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times 9265.9 cm, 180PPI)