

Basic Detail Report



Silo 133: Hoxie Road, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 133: Concrete Stave, 60' x 20', c. 1972, currently in use. Image of a large barn with a stone foundation and miss-matched steel siding. There is a cement block silo next to the barn and a hay escalator on the left, leading into the hay loft. There is snow on the ground and it is still falling.

Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)