Basic Detail Report



9265.9 cm, 180PPI)

Silos 134-136: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 134: Harvestore, 60' x 20', c. 1974, not currently in use. Silo 135: Harvestore, 40' x 20', c 1975, not currently in use. Silo 136: Concrete Stave, 70' x 20', c 1971, not currently in use. Image of a large barn with a stone foundation and miss-matched steel siding. There is a cement block silo next to the barn and a hay escalator on the left, leading into the hay loft. There is snow on the ground and it is still falling.

Dimensions

Digital Resolution: 2736 \times 3648 in., 180PPI (6949.5 \times