

Basic Detail Report



Silos 141-143: County Highway 18, Edmeston, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 141: Clay Tile, 30' x 16', c. 1950, not currently in use. Silo 142: Wooden Stave, 40' x 16', c. 1950, not currently in use. Silo 143: Concrete Stave, 50' x 18', c. 1950, not currently in use. Image of a large barn with three silos, two on the left side and one on the right. There are goats in the pasture directly next to the barn. The front of the barn has white double sliding doors on the front. There is snow on the ground and foot print leading to the barn.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)