

Basic Detail Report



Silos 144 & 145: County Highway 18, Edmeston, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 144: Concrete Stave, 50' x 18', not currently in use.

Silo 145: Concrete Stave, 50' x 16', not currently in use.

Image of two silos in between two sections of a large red barn. There is another smaller barn in front of the red barn and they are all on the other side of a fence. The silo on the right is slightly shorter than the other. There are footprints in the snow leading to where the photo is taken from.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)