

# Basic Detail Report

---



## Silos 147-149: Academy Road, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 147: Concrete Stave, 60' x 18, not currently in use.

Silo 148: Concrete Stave, 60' x 18', not currently in use.

Silo 149: Clay Tile, 30' x 18', not currently in use. Image of a pick up truck parked in a snowy driveway along side of a red barn. There are two silos and a grain bin in front of the truck and a silo on the far side of the barn. There is snow falling and an inch or so of snow already on the ground.

### Dimensions

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x 9265.9 cm, 180PPI)