

# Basic Detail Report

---



9265.9 cm, 180PPI)

## **Silo 159: Beaver Creek Road, Brookfield, NY**

### **Date**

2013-14

### **Medium**

Digital image Jpeg

### **Description**

Silo 159: Concrete Stave, 50' x 16', built c. 1970, current use unknown. Image of a red barn and silo in a snow storm. There are three cupolas on the roof of the barn and a sod ramp leading up to front doors. There are pieces of farm equipment along the side of the barn and another red barn behind the first barn.

### **Dimensions**

Digital Resolution: 2736 x 3648 in., 180PPI (6949.5 x