

Basic Detail Report



Silo 113: Pritchard Road, Plainfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 113: Concrete Stave, 50' x 20', c. 1971, not currently in use. Image of the bottom of a cement silo and the barn it sits next to. The large barn door is slid open and there is

snow on its roof.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)