



Silos 114-116: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 114: Concrete Stave, 60' x 18', c. 1989, not currently in use. Silo 115: Concrete Stave, 70' x 20', c. 1970, not currently in use. Silo 116: Concrete Stave, 40' x 16', c. 1900, not currently in use. Image of a silo at the corner of a white barn. The trees around the silo are starting to pop leaves and the grass is greening up. The hillside in the background is foggy.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)