



## Silos 114-116: Route 8, Brookfield, NY

### Date

2013-14

### Medium

Digital image Jpeg

### Description

Silo 114: Concrete Stave, 60' x 18', c. 1989, not currently in use. Silo 115: Concrete Stave, 70' x 20', c. 1970, not currently in use. Silo 116: Concrete Stave, 40' x 16', c. 1900, not currently in use. Image of two silos on the other side of lines of wrapped silage. One of the tubes of silage is almost gone. The silo on the left is half the height of the second and is missing its roof. Beyond them, there is a large white house and large white barn with another silo next to it.

### Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 × 9265.9 cm, 180PPI)