

Basic Detail Report



9265.9 cm, 180PPI)

Silos 114-116: Route 8, Brookfield, NY

Date

2013-14

Medium

Digital image Jpeg

Description

Silo 114: Concrete Stave, 60' x 18', c. 1989, not currently in use. Silo 115: Concrete Stave, 70' x 20', c. 1970, not currently in use. Silo 116: Concrete Stave, 40' x 16', c. 1900, not currently in use. Image of two silos, side-by-side, along a road. The one on the right is half the height of the other and missing its roof. Behind them, there is a pole barn and wrapped lines of silage. The hillsides beyond the farm are all foggy.

Dimensions

Digital Resolution: 2736 × 3648 in., 180PPI (6949.5 ×